



236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

236.53

SE4
233.76
TARMAC

233.72
GRASS

233.78
TARMAC

233.22
TARMAC

233.10
GRASS

233.25
TARMAC

232.22
TARMAC

232.10
GRASS

232.25
TARMAC

231.22
TARMAC

231.10
GRASS

231.25
TARMAC

230.22
TARMAC

230.10
GRASS

230.25
TARMAC

229.22
TARMAC

229.10
GRASS

229.25
TARMAC

ASSUMED ROUTE OF EXISTING CULVERT
ASSUMED LENGTH 66m GIVING GRADIENT
AT 1 IN 1.3

UNABLE TO SURVEY IN
THIS AREA - NO ACCESS

UNABLE TO SURVEY IN
THIS AREA - NO ACCESS

UNABLE TO SURVEY IN
THIS AREA - NO ACCESS

EXISTING 600mmØ
CULVERT OUTFALL
FROM SITE:
GL234.86
IL233.79

ASSUMED EXISTING
MANHOLE ON
CULVERT.

ASSUMING 1.0m
COVER ON EXISTING
600mmØ CULVERT:
CL230.44
IL228.84

P&W.F
Hi=1.200m

J.R.F
Hi=1.400m

J.R.F
Hi=1.400m

H=1.500m

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

230.00

WOODPILMPTON ROAD

TREE CANOPY

DRY DITCH

GAP IN FENCE

GAP IN FENCE

FENCE ENDS

TARMAC

MANHOLE ON CULVERT

MANHOLE ON CULVERT